

END OF LIFE OF IGX-CVM, IGX-CVM-DS0A, IGX-CVM-E1EC, IGX-CVM-T1EC, AND THE IGX-CVM-TT



Cisco Systems is announcing the End of Sales (EoS) for the IGX-CVM, IGX-CVM-DS0A, IGX-CVM-E1EC, IGX-CVM-T1EC, and the IGX-CVM-TT along with associated back cards, with an effective date of April 13, 2001. Customers will continue to receive Technical Assistance Center (TAC) and RMA support for these modules as noted below (see Milestone Dates).

Comparison Overview

EoL Cisco Product Number	Replacement Card
IGX-CVM	IGX-UVM
IGX-CVM-E1EC	IGX-UVM
IGX-CVM-T1EC	IGX-UVM
IGX-CVM-DS0A	No Replacement
IGX-CVM-TT	No Replacement
BC-550100-J1 (used on IGX-CVM only)	BC-UVI-2J1EC

The IGX-CVM, IGX-CVM-E1EC, and the IGX-CVM-T1EC have the following similarities with the replacement card IGX-UVM:

- Echo Canceller
- T1/E1/J1 back cards
- Modem Detection
- Fax. Detection
- CCS/CAS Signaling
- VAD
- PCM
- ADPCM 32K
- ADPCM 24K
- Transparent Data N x 56K, N x 64K (where N less than or equal to 8)



Note: The differences between the IGX-CVM, IGX-CVM-E1EC, IGX-CVM-T1EC, and the IGX-UVM are:

IGX-CVM/-E1EC/-T1EC	IGX-UVM
No LD-CELP	LD-CELP 16K
No CSA-CELP	CSA-CELP 8K (G.729, G.729A)
No Fax Relay	Fax Relay @ 9600
ADPCM 16	No ADPCM 16, but rather 24K and 32K

Milestone	Effective Date
End of Sales & End of Life Announcement (Internal):	April 13, 2001
End of Sales & End of Life Announcement (External):	April 16, 2001
End of Sales:	July 17, 2001
End of Support/End of Life:	November 2005

Definitions

End of Sale: After this milestone date, these cards will become non-orderable.

End of Support/End of Life: Hardware support, for these products, will cease after this date.

Ordering Information

July 17, 2001 will be the last date to enter orders for these cards. Hardware support, for these cards, will be provided until November 2005. Switch software 9.3 will be the last release supporting these cards. Customers will continue to receive Technical Assistance Center (TAC) and RMA support, for these modules, until November 2005.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy-les-Moulineaux Cedex 9
France
www-europe.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2001 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement. Printed in the USA. AccessPath, AtmDirector, Browse with Me, CCDA, CCDE, CCDP, CCIE, CCNA, CCNP, CCSL, CD-PAC, CiscoLink, the Cisco NetWorks logo, the Cisco Powered Network logo, Cisco Systems Networking Academy, the Cisco Systems Networking Academy logo, Fast Step, Follow Me Browsing, FormShare, FrameShare, GigaStack, IGX, Internet Quotient, IP/VC, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ Logo, iQ Net Readiness Scorecard, MGX, the Networkers logo, Packet, PIX, RateMUX, ScriptBuilder, ScriptShare, SlideCast, SMARTnet, TransPath, Unity, Voice LAN, Wavelength Router, and WebViewer are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, and Empowering the Internet Generation are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BXP, Catalyst, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Enterprise/Solver, EtherChannel, EtherSwitch, FastHub, FastSwitch, IOS, IP/TV, LightStream, MICA, Network Registrar, Post-Routing, Pre-Routing, Registrar, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0102R)