

3M™ Fiber Optic Splice Closure 2178 Accessories

SPLICE TRAYS

PRODUCT NUMBER/ PACKAGING INFO	DESCRIPTION
2170 PKG.(LBS.): 50 EACH (0.10) MIN. ORDER: 50 EACH UPC: 054007-17676	Fiber Optic Splice Sleeve, 3.0 mm x 60 mm Transparent plastic tube and stainless steel rod designed to prevent stress and protect fusion fiber optic splices in field and factory operations.
2171 PKG.(LBS.): 50 EACH MIN. ORDER: 50 EACH UPC: 051115-14547	Fiber Optic Splice Sleeve, 2.4 mm x 60 mm Transparent plastic tube and stainless steel rod designed to prevent stress and protect fusion fiber optic splices in field and factory operations.
2519 PKG: 10 KITS MIN. ORDER: 10 KITS UPC: 051138-57722	Cable Fanout Kit Transitions cable buffer tubes or single tube to fiber tube.
2519-X PKG: 10 KITS MIN. ORDER: 10 KITS UPC: 051138-57723	Cable Fanout Expander Kit Transitions one fiber tube to two fiber tubes.
2520 PKG.(LBS.): 50 EACH (0.90) MIN. ORDER: 50 EACH UPC: 051138-36414	Fiber Tube Transition Tubing, 1 ft. Protects 12 single or four 12-fiber ribbon between trays; cut in one-foot lengths.
2520-3FT PKG.(LBS.): 24 EACH (1.50) MIN. ORDER: 24 EACH UPC: 051138-36647	Fiber Tube Transition Tubing, 3 ft. Protects 12 single or four 12-fiber ribbon between trays; cut in three-foot lengths.
2520-100FT PKG.(LBS.): 1 EACH (1.50) MIN. ORDER: 1 EACH UPC: 051115-26078	Fiber Tube Transition Tubing, 100 ft. Protects 12 single or four 12-fiber ribbon between trays; cut in 100-foot lengths.
2520-6RF-1FT PKG.(LBS.): 50 EACH MIN. ORDER: 50 EACH UPC: 051115-06172	Fiber Tube Trans Tubing 6-12 Fibril 1 ft. Protects 12 single or six 12-fiber ribbon between trays; cut in one-foot lengths.
2520-6RF-100FT PKG.(LBS.): 1 EACH (1.50) MIN. ORDER: 1 EACH UPC: 051115-06173	Fiber Tube Trans Tubing 6-12 Fibril 100 ft. Roll Protects 12 single or six 12-fiber ribbon between trays; cut in 100-foot lengths.
2518 PKG.(LBS.): 6 EACH (1.50) MIN. ORDER: 6 EACH UPC: 051115-26076	Fiber Transition Tube Kit for Loose Buffer Tube The 2518 Kit is a 2 MM fiber transition tube kit for loose buffer tube cables. It is used to transition the fibers from the splice closure slack storage area to the splice tray.
2521-F PKG.(LBS.): 12 PKGS. (0.55) MIN. ORDER: 12 PKGS. UPC: 051138-36412	Fusion Splice Insert, 2 Pack Holds 12 single fusion splices in each insert, used in 3M™ Fiber Splice Organizer Trays 2538/2522/2523. 3.0 mm x 60 mm single fusion heat shrink sleeve required (2170 or equivalent).
2521-FL PKG.(LBS.): 12 PKGS. (0.40) MIN. ORDER: 12 PKGS. UPC: 051138-36413	3M™ Fibrlok™ Splice Insert, 2 Pack Holds six Fibrlok or mass fusion splices in each insert, used in 2538/2522/2523 trays. Accommodates single ceramic rod 12 fiber mass fusion sleeves or double ceramic rod 4 to 6 fiber mass fusion sleeves.
2521-R-12RF-MF-A PKG.(LBS.): 24 EACH MIN. ORDER: 24 EACH UPC: 051115-06176	12RF Mass Fusion Spl Insert, Adhesive Back Adhesive backed splice insert that holds six 3M™ Fibrlok™ Splices or Mass Fusion Splices, used in 2543 trays. Accommodates single ceramic rod 12 fiber mass sleeves or double ceramic rod 4 to 6 fiber mass fusion sleeves.

